

Spin Bike Inspection Report from Coopal Ltd for A N Other

Date: 14/01/201
Bike Model: StarTrac 9-7090-MINTPO
Serial No: SBPN1050-L04067 (01)
Inspected by: Nick Beddall

Inspection Checklist:

| | |
|--|---|
| Frame Integrity & Fixings: | Foot fixings tightened / Some frame corrosion – monitor |
| Frame Feet: | OK |
| Seat Stem, Slide, Sleeve & Pop Pin: | OK |
| Handlebars, slide, sleeve & Pop Pin: | OK |
| Saddle Upholstery, Frame & Clamp: | Saddle frame loose at saddle – requires replacement |
| Brake Adjuster, Mechanism & Pads: | OK - lubed |
| Crank & Crank Arms: | OK |
| Pedals, Cage & Straps: | Excessive wear to pedal shafts – require replacement |
| Drivebelt / Chain: | OK |
| Drivebelt / Guard: | OK |
| Bottom Bracket: | OK |
| Main Flywheel: | OK |
| Lubrication: | OK |
| CE Mark / SWL Marked: | Yes |
| Overall Condition: | Average |
| Is Equipment Safe to Use: | No! |
| Rectification Work Carried out: | Foot fixings tightened / Brake pad lubed |
| Further Rectification Required: | Requires new pedal set and saddle |
| Rectification Timetable: | Rectification should be carried out ASAP |
| Recommended Next Inspection: | April 2014 |
| Signed: | Nick Beddall |